

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 3997 From entrance to location



Photo # 3998 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 3999 Location



Photo # 4000 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4001 Location



Photo # 4002 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4003 Location



Photo # 4004 Unmarked deadman #1

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4005 Unmarked deadman #2



Photo # 4006 Same unmarked deadman from different angle

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4007 Unmarked deadman #3



Photo # 4008 Same unmarked deadman from different angle

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4025 Secondary containment liner needs maintenance



Photo # 4026 Secondary containment liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4027 Secondary containment liner needs maintenance



Photo # 4028 Secondary containment liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC F19 Pad

Location #: 311615



Photo # 4025 Secondary containment liner needs maintenance



Photo # 4026 Secondary containment liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4025 Secondary containment liner needs maintenance



Photo # 4026 Secondary containment liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC F19 Pad
Location #: 311615



Photo # 4053 Improperly marked deadman