

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2023

Submitted Date:

07/30/2023

Document Number:

698600828**FIELD INSPECTION FORM**Loc ID 337973 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290649	WELL	PR	05/18/2007	GW	125-10822	LUEKING 42-19X 5N46W	PR

**General Comment:**

Routine Inspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained County Road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Well sign posted on Meter Shed door.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact information posted on well sign.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Pump Jack belt drive guard noted on ground inside fencing.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Stock Panel Fencing around surface equipment at well location.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
Comment:	Gas Meter Run. Chart in Meter Box dated 7-3-23. Meter Calibration/Test Log dated 8-16-22. Valves open.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric Motor.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Metal Meter Shed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Located 4 anchors. One with Marker. One with Marker down. Two not Marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	08/14/2023
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Chemical Tank and Electric Injection Pump.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve open. Casing valve open.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290649	Type:	WELL	API Number:	125-10822	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve open. Casing valve open. Valves at Meter Run are open. Electronic Well File reflects last Production/Status reported 5/1/2023 and Well Status as PR.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600841	Inspection Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199092">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199092</a>