

**Inspection Photos**  
**Location Name: C Korf 2-19**  
**API Number: 125-06977**



**1. Well sign bracket missing well sign.**



**2. View of Wellhead.**



**Inspection Photos**  
**Location Name: C Korf 2-19**  
**API Number: 125-06977**



**3. View of tubing produced water flowline with seep at hammer union threads.**



**4. View of fluids inside SE corner of fencing. Soil is wet and saturated. Well is in active Pivot Irrigated Corn Field adding to moisture around well location.**



**Inspection Photos**  
**Location Name: C Korf 2-19**  
**API Number: 125-06977**



**5. View of SE corner of well location fencing.**



**6. Well location overview. Center pivot pipe can be seen in background left side of photo just above fencing.**

Inspection Photos  
Location Name: C Korf 2-19  
API Number: 125-06977



7. Well sign at remote Gas Meter Run.



8. Remote Meter Shed.



**Inspection Photos**  
**Location Name: C Korf 2-19**  
**API Number: 125-06977**



**9. Remote Gas Meter Run inside Meter Shed.**



**10. Remote Gas Meter location overview.**