

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2023

Submitted Date:

07/30/2023

Document Number:

698600831**FIELD INSPECTION FORM**Loc ID 303433 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253100	WELL	PR	01/26/1994	GW	125-06977	C. KORF 2-19	PR

**General Comment:**

Routine Inspection.

Inspector found active release in Wellhead area upon arrival during walk around. Seep is on tubing side flowline between valve and hammer union on pipe fittings. Fluids are seeping from hammer union coupling threads. Contacted OWN Resources Field Foreman. He is enroute to repair.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No sign at well site. Sign bracket but no sign in bracket. Looked for sign on ground around well site and did not find one.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/30/2023

Emergency Contact Number:

Comment:	Two track off maintained County Road.	
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	Small seeping active release in Wellhead area. Seep is on tubing side flowline between valve and hammer union on pipe fittings. Fluids are seeping from hammer union coupling threads.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: 07/28/2023

In Containment: No

Comment: Inspector found active release in Wellhead area upon arrival during walk around. Seep is on tubing side flowline between valve and hammer union on pipe fittings. Fluids are seeping from hammer union coupling threads. Contacted OWN Resources Field Foreman. He is enroute to repair.

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stock Panel Fencing at Meter Shed.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve closed. Casing valve open.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 7-26-23. Meter Calibration/Test Log dated 8-16-22. Valves open.		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Chemical Tank and Electric Injection Pump.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Metal Meter Shed at remote Gas Meter Run.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	253100	Type:	WELL	API Number:	125-06977	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Valves at Meter Run are open. Electronic Well File reflects last Production/Status reported 5/1/2023 and Well Status as PR.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600844	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199118">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199118</a>
698600845	Hammer union thread seep.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199119">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199119</a>