

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2023

Submitted Date:

07/30/2023

Document Number:

698600832

FIELD INSPECTION FORM

Loc ID 303434 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253101	WELL	PR	01/26/1994	GW	125-06978	O. LUEKING 10-19	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located at well site.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Well sign posted at remote Gas Meter Run.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information posted on both the Well location and Meter Shed signs.		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Stock Panel Fencing at remote Gas Meter Run.		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:	Gas Meter Run. Chart in Meter Box dated 7-3-23. Meter Calibration/Test Log dated 8-12-22. Valves open.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead. No Rods in well. Appears that tubing maybe in wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Metal Meter Shed at remote Gas Meter Run.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 253101 Type: WELL API Number: 125-06978 Status: PR Insp. Status: PR

Producing Well

Comment: No Rods in well. Appears tubing maybe in well or Sub hung and producing out of casing string. Tubing valve open. Casing not connected. Valves at Meter Run are open. Electronic Well File reflects last Production/Status reported 5/1/2023 and Well Status as PR.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600846	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199137