

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3863 From entrance to location



Photo # 3864 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3867 Location



Photo # 3879 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3880 Location



Photo # 3870 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3871 Debris



Photo # 3872 Weeds/Undesirable plant species

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3873 Weeds/Undesirable plant species



Photo # 3874 Weeds/Undesirable plant species

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3879 Weeds/Undesirable plant species



Photo # 3891 Weeds/Undesirable plant species (secondary containment)

Inspection Photos
Location Name: CAERUS PICEANCE LLC N32 Pad
Location #: 334856



Photo # 3876 Stained soils & gravel on location



Photo # 3888 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC N32 Pad

Location #: 334856



Photo # 3889 Flowline heating insulation open ended



Photo # 3890 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC N32 Pad

Location #: 334856



Photo # 3898 Weeds/Undesirable plant species