

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2023

Submitted Date:

07/25/2023

Document Number:

698600778**FIELD INSPECTION FORM**Loc ID 303931 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253809	WELL	PR	06/15/1995	GW	125-07687	GARDNER 1-27	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained county road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign mounted on meter shed door.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well sign.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel fencing around Pump Jack and Wellhead.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Valves open.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing valve closed. Casing valve open.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Steel Meter Shed.		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Pump Jack power and control panel.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253809	Type:	WELL	API Number:	125-07687	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve closed. Casing valve open. Meter run valves open.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At time of inspection erosion channel was noted starting on the NW corner of stock panel fencing at pumping unit. Channel is approximately 30' long heading down slope off location and is approximately 5' wide at widest point.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Corrective action date adjusted to allow access and repair time during current weather pattern of inclement weather. Addressing issue sooner to prevent further erosion during period of heavy rain is encouraged.

Date: 08/04/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403476184	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6194691
698600808	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6194689