

Inspection Photos

7/31/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 334927

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the location from north, northeast, southeast to south. Photos also show stormwater and erosion control measures to manage stormwater runoff have not been installed prior to, or during dirt-work construction/reclamation activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 3: Photo taken from central areas of the Location. Photo shows reclamation specialist was only able to easily penetrate top couple of inches; compaction issues apparent; Location has not been cross-ripped to a minimum depth of 18 inches.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 4: Photo shows compaction alleviation test-pit performed by Reclamation Specialist on the Location. Photo shows an apparent zone of compaction ~2-4 inches below the soil surface.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 334927



July 31, 2023

Photo 5: Photo taken from the access road, facing north. Operator appears to have ripped only a portion of the access road in one direction. Areas have not been cross-ripped and compaction issues remain apparent. Photo also shows stormwater and erosion control measures to manage stormwater runoff have not been installed prior to, or during dirt-work construction/reclamation activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 6: Photo taken from the access road entrance, facing north. Photo shows section of the access road that has not been reclaimed (above yellow line)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 7: Photo taken from the access road entrance, facing south. Photo shows section of the access road that has not been reclaimed (below yellow line).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 8: Photo shows compaction alleviation test-pit performed by Reclamation Specialist on the access road. Operator appears to have ripped a section of the access road in one direction. Photo shows an apparent zone of compaction remaining at road

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 9: See comments under photo 8.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 10: See comments under photo 8.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 11: Photo shows stormwater and erosion control measures to manage stormwater runoff have not been installed prior to, or during dirt-work construction/reclamation activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 12: Photo shows stormwater and erosion control measures to manage stormwater runoff have not been installed prior to, or during dirt-work construction/reclamation activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 334927



Photo 13: Photo shows stormwater and erosion control measures to manage stormwater runoff have not been installed prior to, or during dirt-work construction/reclamation activities.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources