

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Blackman/14-12 Pad

Location ID: 334544

Date: 8/1/2023



SE Corner of Location – Photo #05293



NE Corner of Location – Photo #05294

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Blackman/14-12 Pad

Location ID: 334544

Date: 8/1/2023



NW Corner of Location – Photo #05295



SW Corner of Location – Photo #05296

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Blackman/14-12 Pad

Location ID: 334544

Date: 8/1/2023



Wellheads – Photo #05297



Separators – Photo #05298

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Blackman/14-12 Pad

Location ID: 334544

Date: 8/1/2023



Tank Battery – Photo #05302



Location Lacks Stabilization – Photo #05300

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Blackman/14-12 Pad

Location ID: 334544

Date: 8/1/2023



Location Lacks Stabilization – Photo #05301



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #05304

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Blackman/14-12 Pad

Location ID: 334544

Date: 8/1/2023



Rill Erosion Running Across Access Road – Photo #05305