

**PIONEER NATURAL RESOURCES**  
**COGCC POST-CONSTRUCTION INSPECTION**

8,9

Lease & Well No. Bigline 32-15<sup>CG</sup> + TR  
 Date Inspected: 8-29-2012  
 Legal Description: 30-15-33S67W  
 Inspected by: S. Rivera  
 % Vegetation: 80%

Maintenance Priority: High / Med / Low NA  
 Pit Freeboard? Yes / No  
 Freeboard Marker? Yes / No  
 Pit Water Level: Empty • 1/4 • 1/2 • 3/4 • Full  
 Overall Pit Condition (nil of cuttings, stormwater sediment etc.): No Ore Pit

Stormwater running to pit? Yes / No  
 Lined / Unlined  
 Signs of Leakage? Yes / No  
 Well Placard? Yes / No  
Both

**BMPs Requiring Maintenance**

BMP	Date Completed	Initials	Actions Requested by Norwest
Wattles (erosion logs)			
Check Dams			
Rip Rap			
Vegetation			
Straw Blankets			
Coconut Blankets			
Diversion Ditch / Berm			
Sediment Pond			
Rills / Washout			
Silt Fence			
Culverts			
Other:			

Dist. from waterbody: — Dist. from County Rd: State Hwy 12  
 Erosion Potential: Low  
 Notes: Recent Seeding & Diversion Work.

**Actions Requested by Pioneer:**

**Actions Taken:**

Assigned to: \_\_\_\_\_ Date: \_\_\_\_\_ Company: \_\_\_\_\_  
 Completed By: \_\_\_\_\_ Date: \_\_\_\_\_ Company: \_\_\_\_\_  
 Follow up Inspection by: \_\_\_\_\_ Date: \_\_\_\_\_

