

TEP
DOE 2-W-21
Location ID:
335256



Location



Location



TEP
DOE 2-W-21
Location ID:
335256



Separators



Cut slope sluffing off. Roots of vegetation is exposed.

TEP
DOE 2-W-21
Location ID:
335256



Location covered with mud. BMP's failing. Well heads.



Location covered with mud. BMP's failing

TEP
DOE 2-W-21
Location ID:
335256



Location covered with mud. BMP's failing



Location covered with mud. BMP's failing

TEP
DOE 2-W-21
Location ID:
335256



Location covered with mud. BMP's failing



Location covered with mud. BMP's failing

TEP
DOE 2-W-21
Location ID:
335256



Tank battery



Vehicle has driven into mud which could lead to tracking issues

TEP
DOE 2-W-21
Location ID:
335256



Vehicle has driven into mud which could lead to tracking issues



Run off

TEP
DOE 2-W-21
Location ID:
335256



Vehicle has driven into mud which could lead to tracking issues



Vehicle has driven into mud which could lead to tracking issues

TEP
DOE 2-W-21
Location ID:
335256



Location covered with mud



Location covered with mud

TEP
DOE 2-W-21
Location ID:
335256



**Cut slope lacks stabilization, riling and erosion.
BMP's failing**



Cut slope lacks stabilization, riling and erosion

TEP
DOE 2-W-21
Location ID:
335256



Cut slope lacks stabilization, riling and erosion



BMP's failing

TEP
DOE 2-W-21
Location ID:
335256



BMP's failing



Cut slope lacks stabilization, riling and erosion

TEP
DOE 2-W-21
Location ID:
335256



Run off



Location covered with mud. Storm water BMP's failing