

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 8/3/2023



SW Entrance to Location – Photo #05429



SE Corner of Location – Photo #05430

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 8/3/2023



NE Corner of Location – Photo #05431



NW Corner of Location – Photo #05432

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 8/3/2023



Wellheads – Photo #05433



Separators – Photo #05434

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 8/3/2023



Tank Battery – Photo #05440



Location Lacks Stabilization – Photo #05438

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 8/3/2023



Location Lacks Stabilization – Photo #05439



Insufficient Cut Slope Erosion Control – Photo #05442

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Piceance/28-05 Pad

Location ID: 334427

Date: 8/3/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05443**



**Insufficient Vehicle Tracking BMPs at Access Road
Entrance/Exit – Photo #05445**