

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2023

Submitted Date:

08/03/2023

Document Number:

694100142**FIELD INSPECTION FORM**Loc ID 472447 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baker, Melissa	(970) 506-9272	melissa.baker@pdce.com	
,		cogccinspection@pdce.com	
,		COGCCInspection@pdce.com	<a href="#">All Inspections</a>

**General Comment:**

This is an environmental inspection for Location ID 472447 PDC Wiedeman 33, 43-21U. Any corrective actions from previous inspections that have not been addressed are still applicable. There were contract personnel on location at the time of this field inspection. The onsite personnel were extracting water from a local ditch for fracking purposes nearby. Photos attached to document site conditions.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

No spills were present at the time of inspection. Field personnel were onsite extracting water from a ditch for fracking purposes.

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 472447 CDP: \_\_\_\_\_

Comment: Site has been mostly decommissioned. Only a meter house remains onsite. Crews were extracting water from nearby ditch for fracking purposes during inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: Offsite sediment washout was observed during inspection.

Corrective Action: Offsite sediment needs to be recovered/pulled back. Stormwater BMPs need to be installed to prevent future washout. Install or repair required BMPs per Rule 1002.f.(2)C. Date: 08/10/2023

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
694100143	photo log	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208835">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208835</a>