

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2023

Submitted Date:

08/05/2023

Document Number:

698600873

## FIELD INSPECTION FORM

 Loc ID 336869 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 66190  
 Name of Operator: OMIMEX PETROLEUM INC  
 Address: 2501 HARWOOD ST STE 1238  
 City: DALLAS State: TX Zip: 75201
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 24 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
McLaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
Hickey, Mike		michael.hickey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280169	WELL	PR	07/01/2021	GW	125-09516	BLEDSOE 16-23-5-45	PR

**General Comment:**

Routine Inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained.		
Corrective Action:	Repair and maintain lease road to comply with rule 603.I.	Date:	09/06/2023
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign located inside well fencing.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact #877-425-4882 posted on well sign is invalid and appears to be disconnected or no longer in service.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/06/2023
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Vegetation growth inside fencing and around wellhead.		
Corrective Action:	Comply with Rule 606	Date:	08/14/2023
Type	DEBRIS		
Comment:	Production related debris left inside wellhead fencing.		
Corrective Action:	Comply with Rule 606	Date:	08/23/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Pump Jack	# 0		corrective date
Comment:	Removed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement Pad. Pump Jack has been removed but cement pad is still inside fencing.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Metal Meter Shed.		

Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	08/17/2023
Type: Deadman # & Marked	# 3		
Comment:	Located 3 marked Deadmen.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Inside Meter Shed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 1-2-23. Meter Calibration/Test Log dated 7-24-20. Well Inlet Valve- Closed. Gas Outlet valve open. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	09/06/2023
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods and tubing in wellbore. Tubing in wellbore. Tubing valve closed. Casing valve closed. Supply gas valve closed.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 280169 Type: WELL API Number: 125-09516 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Pump Jack removed. Rods and tubing in wellbore. Tubing valve closed. Casing valve closed. Well inlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Current production configuration has the well as SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: **Submit required Form 7(s) to COGCC per rule 413.**

Date: 09/06/2023

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600890	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6209258">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6209258</a>