

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Location Overview: Location is within High Priority  
Habitat area & Bald Eagle Nest & Roost sites & in  
close proximity to NSO/Density Habitat areas.  
Section/Township/Range: 27 6S94W**





**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3788 From inspection 708900206 conducted on 03/30/2023 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 4676 Ditch coming out sediment trap/insufficient run off controls/BMP's**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3789 From inspection 708900206 conducted on 03/30/2023 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 4680 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 3790 From inspection 708900206 conducted on 03/30/2023 Ditch coming out sediment trap/insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 4688 Ditch coming out of sediment trap - Insufficient run off controls/BMP's**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 4677 Insufficient run off controls/BMP's**



**Photo # 4683 Insufficient run off controls/BMP's/erosion & transport of sediment**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 4681 Insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 4682 Insufficient run off controls/BMP's/erosion & transport of sediment**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 4684 Insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 4685 Insufficient run off controls/BMP's/erosion & transport of sediment**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 4686 Insufficient run off controls/BMP's/erosion & transport of sediment**



**Photo # 4673 Soils pile near sediment trap (W/NW area of location near fill slope)**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 137-27 pad**  
**Location ID: 324122**



**Photo # 4674 Soils pile near sediment trap (W/NW area of location near fill slope)**