

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2023

Submitted Date:

07/30/2023

Document Number:

708901174

FIELD INSPECTION FORM

Loc ID 334790 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271161	WELL	PR	01/01/2021	GW	045-09845	SHIDELER 30-2 (O19E)	PR
276985	WELL	PR	03/01/2023	GW	045-10562	SHIDELER 19-10 (O19E)	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 07/27/2023 at approximately 11:00 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at CAERUS PICEANCE LLC O19E Pad. Location # 334790 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. Location is approximately 487 yards from Middle Mamm Creek. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Stormwater - Erosion & transport of sediment on location & on lease road with a CA date of 08/14/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Split pad/Remote Location - Wellheads only - Production equipment for these 2 wells is located on the O19EB pad, location # 431050.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Chemical tank - cattle panels		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Chemical tank		

Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 271161 Type: WELL API Number: 045-09845 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 276985 Type: WELL API Number: 045-10562 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Other	Fail					Rill erosion & transport of sediment
Gravel						Sparse
Rip Rap						
		Rip Rap				
Compaction						Light compaction
		Retention Ponds				
		Gravel				Sparse in areas
		Ditches				
		Sediment Traps				
		Other	Fail			Erosion & transport of sediment on lease road

Comment: [1. Rill erosion & transport of sediment on location](#)

[2. Erosion & transport of sediment on lease road \(erosion is on the road starting approximately 30-40 yards from entrance to location\)](#)

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.**

Date: 08/14/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Stormwater for observed compliance issues.	smelserw	07/29/2023
Split pad/Remote Location - Wellheads only - Production equipment for these 2 wells is located on the O19EB pad, location # 431050.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403480771	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199071
708901177	Inspection 708901174 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199069
708901178	Inspection 708901174 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6199070