

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2023

Submitted Date:

08/09/2023

Document Number:

698600896

**FIELD INSPECTION FORM**Loc ID 337910 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

21 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
McLaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
Hickey, Mike		michael.hickey@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289558	WELL	PR	05/01/2022	GW	125-10745	KILLIN 16-22-5-45	PR

**General Comment:**

Routine Inspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained county road. Two track has not been maintained.			
Corrective Action:	Repair and maintain lease road to comply with rule 603.I.			Date: 09/09/2023
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Contents/Quanity/Hazard.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Well sign located at well location.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Well sign posted at remote Gas Meter Run.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.			
Corrective Action:	Install sign to comply with Rule 605.a.			Date: 09/09/2023
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Well location has vegetation growing inside fencing. Remote Gas Meter Run site is over grown with vegetation.			
Corrective Action:	Comply with Rule 606.			Date: 08/17/2023
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Stock Panel Fencing.			
Corrective Action:				Date:
<b>Equipment:</b>				
			corrective date	
Type: Other	# 1			
Comment:	Metal Meter Shed at remote Gas Meter Run.			
Corrective Action:				Date:
Type: Bradenhead	# 0			
Comment:	Bradenhead inaccessible or not visible.			

Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date:	08/20/2023
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve closed, not connected.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Remote Gas Meter Run located on CR BB. Gas Meter Run. Undated Chart in Meter Box. Meter Calibration/Test Log dated 7-16-20. Well Inlet Valve closed. Gas Outlet Valve open. Water Outlet valve closed.			
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date:	09/09/2023
Type: Vertical Separator	# 1			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:	Remote Tank located NE of well off CR BB.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 289558 Type: WELL API Number: 125-10745 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve closed, not connected. Gas Meter Run Valves: Well inlet valve closed, Gas outlet valve open, Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/09/2023

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600909	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213040">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213040</a>