

Inspection Photos
Location Name: Schneller 9-22-5-45
API Number: 125-09609



1. Well sign at well location. Note vegetation.



2. View of Wellhead. Note vegetation.

Inspection Photos
Location Name: Schneller 9-22-5-45
API Number: 125-09609



3. View of Wellhead and Casing valves.



4. Well location overview. Note vegetation.

Inspection Photos

Location Name: Schneller 9-22-5-45

API Number: 125-09609



5. Well sign at remote Gas Meter Run.



6. Meter Shed coming off supports and leaning backwards placing tension on the flowlines.

Inspection Photos
Location Name: Schneller 9-22-5-45
API Number: 125-09609



7. Inlet flowline being bent due to Meter Shed leaning. Note vegetation.



8. View of Chart in Meter Box at time of inspection.

Inspection Photos
Location Name: Schneller 9-22-5-45
API Number: 125-09609

Ominex Meter Test Report

Well Name Schneller 9-22-5-45 Date 7-16-20

Diff. Range 0 to 100 Plate .250
 Static Range 0 to 150
 Temp Average 60

Differential			Static		
Chart Read	Found	Left	Chart Read	Found	Left
0	0	0	0	0	0
100	100	100	150 (250)	150	150 (250)
50	50	50	75 (±50) 125	75	75 (±50) 125
0	0	0	0	0	0

Inspector: [Signature]

2023.08.07 12:51

9. View of Meter Calibration/Test Log located inside Meter Shed.



10. View of remote Meter Run location with Meter House for the Schneller 10-22-5-45 already blown over. Note vegetation.