

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2023

Submitted Date:

08/10/2023

Document Number:

712700500

FIELD INSPECTION FORMLoc ID 325897 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215534	WELL	PR	08/01/2019	CBM	067-07139	MILLER FEDERAL 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Present
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	And meterhouse, cattle panel.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Telemetry		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to meterhouse. Calibrated within one year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment:	Wellhead		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	3" line from wellhead to separator.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215534	Type:	WELL	API Number:	067-07139	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	06/29/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches				
Berms	Pass	Culverts	Pass			
Ditches	Pass	Gravel	Pass			
Compaction	Pass					

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700504	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214105