

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2023

Submitted Date:

08/10/2023

Document Number:

698600903

FIELD INSPECTION FORM

Loc ID 336868 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 2501 HARWOOD ST STE 1238
City: DALLAS State: TX Zip: 75201

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 24 Number of Comments
8 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
, Engineering		dnr_cogccengineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280168	WELL	PR	02/01/2021	GW	125-09515	BOWMAN 8-21-5-44	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained.		
Corrective Action:	Repair and maintain lease road to comply with rule 603.I.	Date:	09/10/2023
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign at well location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/10/2023
Good Housekeeping:			
Type	DEBRIS		
Comment:	Production related debris left at well site.		
Corrective Action:	Comply with Rule 606.	Date:	08/26/2023
Type	WEEDS		
Comment:	Well location has vegetation growing inside fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/18/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock Panel Fencing around Wellhead.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire fencing around location.		
Corrective Action:		Date:	
Equipment:			
			corrective date
Type: Other	# 1		
Comment:	Metal Meter Shed.		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Removed.		

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 11-30-22. Meter Calibration/Test Log dated 8-25-20. Well Inlet Valve open. Gas Outlet Valve open. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	09/10/2023
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	08/21/2023
Type: Deadman # & Marked	# 1		
Comment:	Located one Deadman numarked. Unable to locate remaining three Deadmen.		
Corrective Action:	Install proper guy line markers per Rule 603.j	Date:	08/25/2023
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed, not connected. Casing valve closed.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Inside Meter Shed.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 280168 Type: WELL API Number: 125-09515 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Pump Jack removed. Rods have been removed from the wellbore. Tubing appears to be in the wellbore. Tubing valve closed, not connected. Casing valve closed. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open, Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings at the wellhead the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: **Submit required Form 7(s) to COGCC per rule 413.** Date: 09/10/2023

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600919	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6214269