

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/10/2023

Document Number:

697007868

**FIELD INSPECTION FORM**Loc ID 310411 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment |
|--------------|-------|---|---------|
| ,            |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 292505      | WELL | TA     | 03/30/2021  | OW         | 123-26371 | LINDBLAD 25-34 | TA          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |             |
|---------------------------|-------------|
| Emergency Contact Number: |             |
| Comment:                  |             |
| Corrective Action:        | Date: _____ |

|                           |  |       |            |
|---------------------------|--|-------|------------|
| <b>Good Housekeeping:</b> |  |       |            |
| Type                      | WEEDS  |       |            |
| Comment:                  | Weeds have grown around the wellhead area with debris inside of wellhead fencing, see attached photos. |       |            |
| Corrective Action:        | Comply with Rule 606   | Date: | 08/31/2023 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Panel    |       |  |
| Corrective Action: |          | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Flow Line                   | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

|                           |   |  |       |
|---------------------------|---|--|-------|
| Type: Bird Protectors     | # 2                                     |  |       |
| Comment:                  |   |  |       |
| Corrective Action:        |   |  | Date: |
| Type: Pig Station         | # 2                                     |  |       |
| Comment:                  |   |  |       |
| Corrective Action:        |   |  | Date: |
| Type: Ancillary equipment | # 1                                     |  |       |
| Comment:                  | ECD scrubber                            |  |       |
| Corrective Action:        |   |  | Date: |
| Type: Bradenhead          | # 1                                     |  |       |
| Comment:                  | Bradenhead valve is exposed at surface. |  |       |
| Corrective Action:        |   |  | Date: |
| Type: Gas Meter Run       | # 1                                     |  |       |
| Comment:                  |   |  |       |
| Corrective Action:        |   |  | Date: |
| Type: Plunger Lift        | # 1                                     |  |       |
| Comment:                  |   |  |       |
| Corrective Action:        |   |  | Date: |

**Tanks and Berms:**

|                    |   |          |                |         |        |       |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents           | # | Capacity | Type           | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | 100 BBLS | PBV FIBERGLASS |         | ,      |       |
| Comment:           |   |          |                |         |        |       |
| Corrective Action: |   |          |                |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                 |          |  |
|-----------------|----------|--|
| Condition       | Adequate |  |
| Other (Content) |          |  |

|                    |          |                     |             |                     |             |       |
|--------------------|----------|---------------------|-------------|---------------------|-------------|-------|
| Other (Capacity)   |          |                     |             |                     |             |       |
| Other (Type)       |          |                     |             |                     |             |       |
| <b>Berms</b>       |          |                     |             |                     |             |       |
| Type               | Capacity | Permeability (Wall) |             | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    |             | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |             |                     |             |       |
| Corrective Action: |          |                     |             |                     |             | Date: |
| Contents           | #        | Capacity            | Type        | Tank ID             | SE GPS      |       |
| PRODUCED WATER     | 1        | <50 BBLs            | BV CONCRETE |                     | ,           |       |
| Comment: 48 bbls   |          |                     |             |                     |             |       |
| Corrective Action: |          |                     |             |                     |             | Date: |
| <b>Paint</b>       |          |                     |             |                     |             |       |
| Condition          | Adequate |                     |             |                     |             |       |
| Other (Content)    |          |                     |             |                     |             |       |
| Other (Capacity)   |          |                     |             |                     |             |       |
| Other (Type)       |          |                     |             |                     |             |       |
| <b>Berms</b>       |          |                     |             |                     |             |       |
| Type               | Capacity | Permeability (Wall) |             | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    |             | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |             |                     |             |       |
| Corrective Action: |          |                     |             |                     |             | Date: |
| <b>Venting:</b>    |          |                     |             |                     |             |       |
| Yes/No             | NO       |                     |             |                     |             |       |
| Comment:           |          |                     |             |                     |             |       |
| Corrective Action: |          |                     |             |                     |             | Date: |
| <b>Flaring:</b>    |          |                     |             |                     |             |       |
| Type               |          |                     |             |                     |             |       |
| Comment:           |          |                     |             |                     |             |       |
| Corrective Action: |          |                     |             |                     |             | Date: |

**Inspected Facilities**Facility ID: 292505 Type: WELL API Number: 123-26371 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Form 6A #403118488

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 08/21/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 24 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| <p><a href="#">COGCC Inspection Report Summary</a><br/> On Thursday 8/10/2023 at approximately 12:25 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Lindblad 25-34 location #310411 in Weld County, Colorado.<br/> While there, I observed weeds and debris around the wellhead area. The following possible compliance issues were observed: Rule 606. with a corrective action date of 8/31/2023.<br/> A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/> This is a summary of the inspection report.</p> | petersont | 08/10/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697007869    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215063">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215063</a> |