

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/10/2023

Document Number:

699107164

**FIELD INSPECTION FORM**Loc ID 317921 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10528

Name of Operator: ARCH OIL &amp; GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 305

City: DALLAS State: TX Zip: 75248

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	All Inspections
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240185	WELL	SI	03/01/2020	OW	123-07973	CUYKENDALL-LAUCK 2	SI

**General Comment:**

This is an inspection on the well

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access to the well is covered in overgrown vegetation and needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 09/22/2023
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign does not reflect current operator.		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 09/22/2023
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil next to the engine on the pumping unit needs to be removed. See attached photo		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 09/22/2023
Type	WEEDS		
Comment:	Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.		Date: 09/22/2023
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No <input type="checkbox"/>			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	#		corrective date
Comment:	cant see BH due to overgrown vegetation		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment:	ng engine		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240185 Type: WELL API Number: 123-07973 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: si

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/15/2019

Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: No updated annual BH test on file. Submit reports. Form 17 #402266686 indicates it was last tested on 8/15/19

09/22/2023

Corrective Action: Submit reports as per Rule 207.

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 8/10/23 at approximately 0656hrs I, Inspector Adam Burns, Conducted an on-site inspection at Cuykendall-Lauck 2 of Arch Oil &amp; Gas LLC. API #05-123-07973 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well needs an MIT. Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. With a Corrective Action date of 9/22/23</p> <p>Well sign does not reflect current operator. Install sign to comply with Rule 605.g. With a Corrective Action date of 9/22/23</p> <p>Stained soil next to the engine on the pumping unit needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation in and around the well location, needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>No updated annual BH test on file. Submit reports. Form 17 #402266686 indicates it was last tested on 8/15/19. Submit reports as per Rule 207. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	08/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107165	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215225">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6215225</a>