

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2023

Submitted Date:

08/03/2023

Document Number:

694100142**FIELD INSPECTION FORM**Loc ID 472447 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baker, Melissa	(970) 506-9272	melissa.baker@pdce.com	
,		cogccinspection@pdce.com	
,		COGCCInspection@pdce.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 472447 PDC Wiedeman 33, 43-21U. Any corrective actions from previous inspections that have not been addressed are still applicable. There were contract personnel on location at the time of this field inspection. The onsite personnel were extracting water from a local ditch for fracking purposes nearby. Photos attached to document site conditions.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: No spills were present at the time of inspection. Field personnel were onsite extracting water from a ditch for fracking purposes.

☐ Multiple Spills and Releases?
Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 472447 CDP: _____

Comment: Site has been mostly decommissioned. Only a meter house remains onsite. Crews were extracting water from nearby ditch for fracking purposes during inspection.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: Offsite sediment washout was observed during inspection.

Corrective Action: Offsite sediment needs to be recovered/pulled back. Stormwater BMPs need to be installed to prevent future washout. Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 08/10/2023

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403487560	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208870
694100143	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208835