

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2023

Submitted Date:

08/04/2023

Document Number:

698600870

**FIELD INSPECTION FORM**Loc ID 337033 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

9 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
Pesicka, Conor		conor.pesicka@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
, Engineering		dnr_cogccengineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Hickey, Mike		michael.hickey@state.co.us	
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281786	WELL	PR	12/01/2021	GW	125-09717	BLEDSE 12-26-5-45	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained and is over grown and covered in vegetation.		
Corrective Action	Repair and maintain lease road to comply with rule 603.l.	Date:	09/06/2023

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign located inside well fencing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact #877-425-4882 posted on well sign is invalid and appears to be disconnected or no longer in service.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 09/06/2023

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Cement Pad and production related debris left inside wellhead fencing.		
Corrective Action:	Comply with Rule 606	Date:	09/06/2023
Type	WEEDS		
Comment:	Well location is over grown with vegetation.		
Corrective Action:	Comply with Rule 606	Date:	08/15/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	08/17/2023
Type: Other	# 1		
Comment:	Cement Pad. Pump Jack has been removed but cement pad is still inside fencing.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		

Comment:	Removed.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods removed from wellbore. Tubing in wellbore. Tubing valve closed but valve is bad and gas is leaking out of open ended valve. Tubing is not connected to flowline. Casing valve closed. Well is leaking at wellhead cap between packing and tubing.		Date:	
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date:	08/03/2023
Type: Gas Meter Run	# 1			
Comment:	Gas Meter Run. Chart in Meter Box dated 1-5-23. Meter Calibration/Test Log dated 7-17-20. Inlet valves open. Gas outlet is open. Water outlet is closed.  Meter not calibrated annually.		Date:	
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date:	09/06/2023
Type: Other	# 1			
Comment:	Metal Meter Shed.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 0			
Comment:	Removed.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Pump Jack Power and Control Panel.		Date:	
Corrective Action:			Date:	

**Venting:**

Yes/No	YES		
Comment:	Well is leaking gas at the well cap and out of the open ended tubing valve.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 08/03/2023

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 281786 Type: WELL API Number: 125-09717 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Pump Jack removed. Rods removed from wellbore. Tubing in wellbore. Tubing is not connected to flowline. Casing valve closed. Valves at Meter Run are open. Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Current production configuration has the well as SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/07/2023

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403487584	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208949</a>
698600885	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208946">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208946</a>
698600886	Wellhead Release at Wellhead Cap Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208947">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208947</a>
698600887	Gas Leak at Tubing Valve Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208948">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208948</a>