

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/02/2023

Submitted Date:

08/04/2023

Document Number:

698600882

FIELD INSPECTION FORMLoc ID 421380 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

23 Number of Comments

9 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Hickey, Mike		michael.hickey@state.co.us	
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
, Engineering		dnr_cogccengineering@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421377	WELL	PR	10/01/2021	GW	125-11952	Bledsoe 5-26-5-45	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained and is over grown and covered in vegetation. Well is in active pivot irrigated field (Corn).		
Corrective Action	Repair and maintain lease road to comply with rule 603.I.	Date:	09/06/2023

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Well sign at the remote Meter Shed. Sign has incorrect API number. Verified well for facility using Chart and Calibration Log. API number on sign is 05-125-11964-00 and should be 05-125-11952-00.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/06/2023
Type	WELLHEAD		
Comment:	Well sign located inside well fencing.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents/Quantity/Hazard.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: The emergency contact #877-425-4882 posted on well signs is invalid and appears to be disconnected or no longer in service.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 08/06/2023

Good Housekeeping:

Type	WEEDS		
Comment:	Remote equipment site is over grown with vegetation.		
Corrective Action:	Comply with Rule 606.	Date:	08/21/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Stock Panel and Post and Wire Fencing around Remote Meter Run and Produced Water Tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Liquids Knock Out Vessel inside meter shed.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Metal Meter Shed at remote Gas Meter Run.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located N of well at fence line. Remote Gas Meter Run located N of well at fence line. Chart in Meter Box dated 1-5-23. Meter Calibration/Test Log dated 7- 17-20. Valves: Gas Sales out is open. Water out is closed. Flowline in appears to be closed. Valve is bad. Meter not calibrated annually.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	09/06/2023
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	08/16/2023
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve closed and not connected to flowline. Wellhead is releasing gas at wellhead cap between packing and tubing.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	08/03/2023
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Well is venting gas at wellhead cap.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).	Date:	08/03/2023
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 421377 Type: WELL API Number: 125-11952 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Rods removed from wellbore. Tubing in wellbore. Tubing valve is closed. Casing valve is closed and not connected to flowline. Valves at Meter Run are closed. Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Current production configuration has the well as SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/06/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403487565	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208874
698600883	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208838
698600884	Leak at Wellhead Video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6208839