

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



NE Corner of Location – Photo #05567



NW Corner of Location – Photo #05658

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



SW Corner of Location – Photo #05659



SE Corner of Location – Photo #05660

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Wellheads – Photo #05661



Separators – Photo #05662

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Tank Battery – Photo #05666



Methanol Tank Label Does Not State Tank Capacity – Photo #05665

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Separator Hatch Unsecured – Photo #05663



Damaged Berm Liner – Photo #05667

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Damaged Berm Liner – Photo #05668



Location Lacks Stabilization – Photo #05670

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Location Lacks Stabilization – Photo #05671



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05672**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Rill Erosion Cutting Through Lease Road – Photo #05674



Rill Erosion Cutting Through Lease Road – Photo #05676

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 8/8/2023



Rill Erosion Cutting Through Lease Road – Photo #05677