

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 8/8/2023



North Side of Location – Photo #05679



South Side of Location – Photo #05680

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 8/8/2023



Aug 8, 2023 at 11:09:49
Parachute CO 81635
United States



Aug 8, 2023 at 11:11:11
Parachute CO 81635
United States

Wellhead – Photo #05681

Separator – Photo #05685

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 8/8/2023



Tank Battery – Photo #05683



Location Lacks Stabilization – Photo #05689

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 8/8/2023



Location Lacks Stabilization – Photo #05690



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #05691**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 8/8/2023



Rill Erosion Cutting Through Lease Road – Photo #05693



Rill Erosion Cutting Through Lease Road – Photo #05694

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 8/8/2023



Check Dam Needs Maintenance – Photo #05692



Check Dam Needs Maintenance – Photo #05695