

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Location Overview: Location is approximately 285 yards from West Mamm Creek. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Section/Township/Range: 13 7S93W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5280 Erosion & transport of sediment off location (N/NW edge of pad behind ROLES 13-14A & COUEY 24-1C separator units)

Photo # 5281 Erosion & transport of sediment off location (N/NW edge of pad behind ROLES 13-14A & COUEY 24-1C separator units)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5283 Erosion & transport of sediment off location (N/NW edge of pad behind ROLES 13-14A & COUEY 24-1C separator units)

Photo # 5284 Erosion & transport of sediment off location (N/NW edge of pad behind ROLES 13-14A & COUEY 24-1C separator units)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5301 Rip Rap Run/BMP's need maintenance (East edge of location near tank battery)



Photo # 5302 Rip Rap Run/BMP's need maintenance (East edge of location near tank battery)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5303 Rip Rap Run/BMP's need maintenance (East edge of location near tank battery)



Photo # 5304 Erosion & transport of sediment/BMP's need maintenance (East edge of location near tank battery)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5305 Erosion & transport of sediment (East edge of location near tank battery)



Photo # 5307 Erosion & transport of sediment (East edge of location near tank battery)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5308 Erosion & transport of sediment (East edge of location near tank battery)



Photo # 5312 Erosion & transport of sediment (East edge of location near tank battery)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5313 Erosion & transport of sediment (East edge of location near tank battery)



Photo # 5314 Erosion & transport of sediment (East edge of location near tank battery)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC P13W Pad
Location #: 334576



Photo # 5321 Culvert outlet (at beginning of spur road to location)



Photo # 5322 Unable to locate culvert inlet, appears to be buried under large amount of sediment - Culvert/BMP's need maintenance (at beginning of spur road to location) Culvert/BMP's need maintenance.