

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5242 From entrance to Location



Photo # 5243 From entrance to Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5244 Location



Photo # 5245 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5246 Location



Photo # 5259 Open ended load line

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5262 Open ended load line



Photo # 5260 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5261 Holes in containment liner/liner needs maintenance



Photo # 5263 Hole in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5264 Hole in containment liner/liner needs maintenance



Photo # 5265 Hole in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N18 Pad
Location #: 334933



Photo # 5266 Hole in containment liner/liner needs maintenance



Photo # 5268 Holes in containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC N18 Pad

Location #: 334933



Photo # 5269 Hole in containment liner/liner needs maintenance



Photo # 5279 Hole in containment liner/liner needs maintenance