

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 5451 From entrance to location



Photo # 5452 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 5454 Location



Photo # 5455 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 5456 Location



Photo # 55457 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2067 From Inspection 708900897 conducted on 06/27/2023 Hole in liner/liner needs maintenance



Photo # 5467 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2069 From Inspection 708900897 conducted on 06/27/2023 Hole in liner/liner needs maintenance

Photo # 5470 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 2071 From Inspection 708900897 conducted on 06/27/2023 Holes in liner/liner needs maintenance



Photo # 5520 Holes in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC K17E Pad
Location #: 334791



Photo # 1665 From Inspection 708900897 conducted on 06/27/2023 Hole in liner/liner needs maintenance



Photo # 5523 Hole in liner/liner needs maintenance