

Inspection Photos

API: 011-06018

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 8/9/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 1. Facing south along the access road. The two track road remains but vegetation appears to have mostly re-established along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 2. Facing southeast toward the location. The location consists primarily of undesirable weeds (*Kochia* sp.) and bare soil. The location has not reestablished a uniform vegetation cover of 80% of reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 3. Facing southwest toward the location. The location consists primarily of undesirable weeds (*Kochia* sp.) and bare soil. The location has not reestablished a uniform vegetation cover of 80% of reference area levels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 4. Disturbed 1 transect facing south at the location.



Photo 5. Disturbed 1 transect facing north at the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 6. Disturbed 2 transect facing west at the location.



Photo 7. Disturbed 2 transect facing east at the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 8. Facing northwest at the undisturbed reference area.



Photo 9. Facing southeast at the undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 10. Drone aerial photo facing west down toward the location. There are areas bare vegetation which appear to be impacted from the wellsite operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 11. Drone aerial photo facing north down toward the location. The inspectors truck is shown in the upper left for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 12. Drone aerial photo facing east down toward the location. There are areas bare vegetation which appear to be impacted from the wellsite operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Inspection Photos



Photo 13. Drone aerial photo facing southeast toward the surrounding undisturbed reference area which has a uniform perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06018 | Date: 8/9/2023

Cover Data

Date: 8/9/23 Inspected By: Ryan Costa

Location/Operator: State 918-S1 Renegade Oil + Gas

[illegible]

2nd= second hit; P= plant species present but not hit