

Inspection Photos

API: 011-06194

Operator: FOUNDATION ENERGY
MANAGEMENT

Inspection Date: 8/9/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 8/9/2023

Inspection Photos




Photo 1. 2012 Aerial photo shows approximate disturbance of the location. The yellow line depicts the fence line which is also shown in the following photos for reference.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing north toward the location. This area about 60'x 10' has not established vegetation and may have compacted soils however the perennial vegetation at the west side of the location appears to be progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 3. Facing north at the location. The perennial vegetation at the west side of the location appears to be progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 4. Northeast side of the location facing southeast. This area of the location where pit was location has not established desirable vegetation and consists mostly of undesirable weeds (Kochia). Red arrow points to the fence line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 5. East side of the location facing southeast. This area of the location where pit was location has not established desirable vegetation and consists mostly of undesirable weeds (Kochia). Red arrow points to the fence line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 6. East side of the location facing east at the fence line. This area of the location where pit was location has not established desirable vegetation and consists mostly of undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 7. East side of the location facing southeast at the fence line. This area of the location where pit was location has not established desirable vegetation and consists mostly of undesirable weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed reference area.

