

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2023

Submitted Date:

08/09/2023

Document Number:

698600894

FIELD INSPECTION FORMLoc ID 337919 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

21 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Hickey, Mike		michael.hickey@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Quint, Craig		craig.quint@state.co.us	E Compliance Supervisor
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	7/16/2023
Chambers, Kit		Kchambers@ravenwoodlabs.com	7/16/2023
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289686	WELL	PR	01/01/2022	GW	125-10759	BLEDSE 14-24-5-45	PR

General Comment:

Routine Inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track off maintained county road. Two track has not been maintained.		
Corrective Action	L Repair and maintain lease road to comply with rule 603.l.	Date:	09/09/2023
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign on Meter Shed.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	09/09/2023
Good Housekeeping:			
Type	WEEDS		
Comment:	Well location has vegetation growing inside fencing.		
Corrective Action:	Comply with Rule 606.	Date:	08/17/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock Panel Fencing around surface equipment at well location.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire fencing around well location.		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve closed, not connected.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas Meter Run. Chart in Meter Box dated 12-1-22. Meter Calibration/Test Log is not on location.. Well Inlet Valve closed. Gas Outlet Valve open. Water Outlet valve open.		
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).	Date:	08/20/2023
Type: Other	# 1		

Comment:	Metal Meter Shed.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 0			
Comment:	Bradenhead inaccessible or not visible.		Date:	
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date:	08/20/2023
Type: Deadman # & Marked	# 4			
Comment:	Located 4 unmarked Deadmen.		Date:	
Corrective Action:	Install proper guy line markers per Rule 603.j		Date:	08/24/2023
Type: Vertical Separator	# 1			
Comment:	Inside Meter Shed.		Date:	
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 289686 Type: WELL API Number: 125-10759 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

Rods have been removed from the wellbore. Tubing appears to be in the wellbore.
Tubing valve closed. Casing valve closed, not connected to flowline. Gas Meter Run
Valves: Well inlet valve closed, Gas outlet valve open, Water outlet valve open.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as
PR. Based on current valve settings at the well location the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting
monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/09/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No noted stormwater issues at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403491240	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6212734
698600906	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6212733