

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2023

Submitted Date:

08/09/2023

Document Number:

698600900

FIELD INSPECTION FORM

 Loc ID: 337967
 Inspector Name: St John, William (Cal)
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 25 Number of Comments
- 10 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 66190
 Name of Operator: OMIMEX PETROLEUM INC
 Address: 2501 HARWOOD ST STE 1238
 City: DALLAS State: TX Zip: 75201
Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|-------|----------------------------------|-------------------------|
| McGlaughlin, Dennis | | Dmac@ravenwoodlabs.com | 7/16/2023 |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Ferrin, Jeremy | | jeremy.ferrin@state.co.us | Enforcement Officer |
| Leonard, Mike | | mike.leonard@state.co.us | Compliance Manager |
| , Engineering | | dnr_cogccengineering@state.co.us | |
| Kirschner, Steven | | steven.kirschner@state.co.us | Enforcement Supervisor |
| Chambers, Kit | | Kchambers@ravenwoodlabs.com | 7/16/2023 |
| Quint, Craig | | craig.quint@state.co.us | E Compliance Supervisor |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 290424 | WELL | PR | 05/01/2022 | GW | 125-10815 | STRUCKMEYER 6-22-5-45 | PR |

General Comment:

Routine Inspection.

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained county road. Two track has not been maintained | | |
| Corrective Action: | Repair and maintain lease road to comply with rule 603.l. | Date: | 09/09/2023 |
| Overall Good: | <input type="checkbox"/> | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign posted on Meter Shed. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service. | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | Date: | 09/09/2023 |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Production related debris left inside wellhead fencing. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 09/09/2023 |
| Type | WEEDS | | |
| Comment: | Well location has vegetation growing inside fencing. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 08/17/2023 |
| Overall Good: | <input type="checkbox"/> | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: | No | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock Panel Fencing is at well site but not assembled. | | |
| Corrective Action: | Repair and maintain fencing to comply with rule 603.h | Date: | 08/14/2023 |
| Type | LOCATION | | |
| Comment: | Post and wire fencing. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: | Ancillary equipment | # 1 | corrective date |
| Comment: | Pump Jack Power and Control Panel. | | |
| Corrective Action: | | Date: | |
| Type: | Bradenhead | # 0 | |
| Comment: | Bradenhead inaccessible or not visible. | | |

| | | | |
|---------------------------|---|-------|------------|
| Corrective Action: | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). | Date: | 08/20/2023 |
| Type: Prime Mover | # 0 | | |
| Comment: | Removed. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas Meter Run. Chart in Meter Box dated 9-1-22. Meter Calibration/Test Log dated 7-16-20. Well Inlet Valve maybe closed. Gas Outlet Valve maybe closed. Water Outlet valve closed. Bad valves on flowlines. | | |
| Corrective Action: | Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14). | Date: | 08/25/2023 |
| Type: Other | # 1 | | |
| Comment: | Cement Pad. Pump Jack has been removed but cement pad is still on site. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve maybe closed, bad valve. | | |
| Corrective Action: | Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14). | Date: | 08/25/2023 |
| Type: Other | # 1 | | |
| Comment: | Metal Meter Shed. | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | Located 4 deadmen. All markers are down. | | |
| Corrective Action: | Install proper guy line markers per Rule 603.j | Date: | 08/24/2023 |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 0 | | |
| Comment: | Removed. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 290424 Type: WELL API Number: 125-10815 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Rods removed. Tubing in wellbore. Tubing valve closed. Casing valve maybe closed, bad valve. Gas Meter Run Valves: Well inlet valve maybe closed, bad valve. Gas outlet valve maybe closed, bad valve. Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: **Submit required Form 7(s) to COGCC per rule 413.**

Date: 09/09/2023

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403492238 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213662 |
| 698600914 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213661 |