

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2023

Submitted Date:

08/09/2023

Document Number:

699107156**FIELD INSPECTION FORM**Loc ID 331882 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 65110Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH State: NH Zip: 03801**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------------|-----------------------|---------------------------------|
| Forma, Joseph | 603-427-2099 x111 | joeforma@obenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-----------------------------|-------------|
| 331882 | LOCATION | AC | | | - | LOST CREEK-63N62W 20NENE | AC |

General Comment:[This is an inspection on the Tank Battery](#)

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Pit needs capacity label. See attached photo | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 09/22/2023 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|----------|
| Emergency Contact Number: | |
| Comment: | Adequate |
| Corrective Action: | |
| Date: | |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Overgrown vegetation around the tank battery needs to be removed for good housekeeping. See attached photos | | |
| Corrective Action: | Comply with Rule 606. | Date: | 09/22/2023 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|----------------|---|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | | PBV FIBERGLASS | | 40.218000,-104.342400 |

| | | | | | | | |
|--------------------|--|---|--|--|--|-------|--|
| Comment: | | NFPA placard is weathered and will need to be replaced in the near future | | | | | |
| Corrective Action: | | | | | | Date: | |

Paint

| | | | | | | |
|------------------|--|--|--|--|--|--|
| Condition | | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |

Berms

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

| | | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 40.218000,-104.342400 | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Paint

| | | | | | | | |
|------------------|----------|--|--|--|--|--|--|
| Condition | Adequate | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |

Berms

| | | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|-------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Venting:

| | | | | | | | |
|--------------------|----|--|--|--|-------|--|--|
| Yes/No | NO | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | Date: | | |

Flaring:

| | | | | | |
|--------------------|--|--|--|--|-------|
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Inspected FacilitiesFacility ID: 331882 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: active tank battery

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Tuesday 8/8/23 at approximately 1010hrs I, Inspector Adam Burns, Conducted an on-site inspection at Lost Creek-63N62W 20NENE Tank Battery of O'Brien Energy Resources Corp.</p> <p>Location ID #331882 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Pit needs capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 9/22/23</p> <p>Overgrown vegetation around the tank battery needs to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p> | burnsa | 08/09/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403492021 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213461 |
| 699107157 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6213443 |