

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5898 From entrance to location



Photo # 5899 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5902 Location



Photo # 5903 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5904 Location



Photo # 5905 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5906 Location




Photo # 5911 Flowline heating insulation open ended

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5918 Flowline heating insulation open ended



Photo # 5919 Flowline heating insulation open ended

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5920 Debris




Photo # 5921 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5922 Stained gravel in secondary containment



Photo # 5925 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5923 Hole in liner/liner needs maintenance



Photo # 5924 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5926 Hole in liner/liner needs maintenance



Photo # 5927 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC N1B Pad
Location #: 334934



Photo # 5928 Hole in liner/liner needs maintenance



Photo # 5929 Hole in liner/liner needs maintenance