

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2023

Submitted Date:

08/17/2023

Document Number:

698600922

**FIELD INSPECTION FORM**Loc ID 337148 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 66190

Name of Operator: OMIMEX PETROLEUM INC

Address: 2501 HARWOOD ST STE 1238

City: DALLAS State: TX Zip: 75201

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

11 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	Enforcement Officer
Chambers, Kit		Kchambers@ravenwoodlabs.com	
McGlaughlin, Dennis		Dmac@ravenwoodlabs.com	
Kirschner, Steven		steven.kirschner@state.co.us	Enforcement Supervisor
Leonard, Mike		mike.leonard@state.co.us	Compliance Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283331	WELL	PR	07/01/2014	GW	125-09854	BENNETT STATE 8-16-5-45	PR

**General Comment:**

Routine Inspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained county road. Two track has not been maintained.			
Corrective Action	Repair and maintain lease road to comply with rule 603.I.		Date:	09/23/2023
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Well sign at remote Gas Meter Run.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Well sign at well location.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Emergency contact #877-425-4882 posted on well sign at remote Gas Meter Run is invalid and appears to be disconnected or no longer in service.			
Corrective Action:	Install sign to comply with Rule 605.a.			Date: 09/18/2023
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Remote Gas Meter Run location has vegetation growing inside and around fencing.			
Corrective Action:	Comply with Rule 606.		Date:	08/25/2023
Type	DEBRIS			
Comment:	Production related debris left at wellhead.			
Corrective Action:	Comply with Rule 606.		Date:	09/02/2023
Type	WEEDS			
Comment:	Well location has vegetation growing around wellhead and remaining equipment.			
Corrective Action:	Comply with Rule 606.		Date:	08/25/2023
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	OTHER			
Comment:	Stock Panel Fencing around remote Gas Meter Shed.			
Corrective Action:			Date:	
Type				
Comment:	At well location.			
Corrective Action:			Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Rods removed. Tubing in wellbore with ball vavle installed at joint collar. Tubing is approximately 6' out of well cap. Tubing valve closed. Casing valve appears to be closed, valve is bad. Well is leaking at the well cap and at the tubing valve.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 08/11/2023
Type: Prime Mover	# 0		
Comment:	Removed.		
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 08/28/2023
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR BB.  Gas Meter Run. Chart in Meter Box is undated. Meter Calibration/Test Log dated 7-15-20. Well Inlet Valve appears to be closed (Bad valve). Gas Outlet Valve open. Water Outlet valve closed.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 09/18/2023
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Inside remote Meter Shed.		
Corrective Action:			Date:
Type: Pump Jack	# 0		
Comment:	Removed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Metal Meter Shed. Shed is nearly off concrete supports and leaning placing tension on inlet/outlet flowlines.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 09/02/2023

**Venting:**

Yes/No	YES		
Comment:	Well is currently venting gas at the well cap and uncapped tubing valve.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14).		Date: 08/11/2023

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 283331 Type: WELL API Number: 125-09854 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Rods removed and tubing in wellbore. Tubing valve closed and not connected. Casing valve appears to be closed. Remote Gas Meter Run Valves: Well inlet valve is bad but appears to be closed, Gas outlet valve open, Water outlet valve closed.

Electronic Well File reflects last Production/Status reported 8/1/2022 and Well Status as PR. Based on current valve settings the well is SI.

Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.

Date: 09/18/2023

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698600944	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222948">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222948</a>
698600945	08/10/2023 Well CAP Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222949</a>
698600946	08/10/2023 Tubing Valve Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222950">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6222950</a>