

Inspection Photos

ID: 484359

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 8/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:484359 | Date: 8/15/2023

Inspection Photos



Photo 1. Facing east toward the access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

ID:484359 | Date: 8/15/2023

Inspection Photos



Photo 2. Facing east toward the wellsite. Drilling was in process at the time of inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:484359 | Date: 8/15/2023

Inspection Photos



Photo 3. The cuttings pile is not stored with line and berm according to waste mng. Plan.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:484359 | Date: 8/15/2023

Inspection Photos



Photo 4. Facing northwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:484359 | Date: 8/15/2023

Inspection Photos



Photo 5. Facing south toward the reclaimed flowline.



Inspection Photos



Photo 6. West side of the location facing south. Straw wattles are installed along the up and down gradient side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:484359 | Date: 8/15/2023