

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2023

Submitted Date:

08/17/2023

Document Number:

702402227

**FIELD INSPECTION FORM**

Loc ID 306548 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                    | Comment                         |
|--------------|-------|--------------------------|---------------------------------|
| ,            |       | COGCCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 289677      | WELL | TA     | 03/12/2019  | OW         | 123-24893 | CANNON-USX W 15-8 | TA          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |  |
|----------------------|---|-------|--|
| <b>Signs/Marker:</b> |   |       |  |
| Type                 | WELLHEAD  |       |  |
| Comment:             | adequate  |       |  |
| Corrective Action:   |   | Date: |  |
| Type                 |   |       |  |
| Comment:             | See Inspection Doc # 699305081 for related shared facilities and equipment. |       |  |
| Corrective Action:   |   | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Fencing/:</b>   |   |       |  |
| Type               | WELLHEAD  |       |  |
| Comment:           | Ag panel  |       |  |
| Corrective Action: |   | Date: |  |
| Type               |   |       |  |
| Comment:           | See Inspection Doc # 699305081 for related shared facilities and equipment. |       |  |
| Corrective Action: |   | Date: |  |

|                    |   |       |                 |
|--------------------|---|-------|-----------------|
| <b>Equipment:</b>  |   |       | corrective date |
| Type: Bradenhead   | # 1   |       |                 |
| Comment:           | exposed at surface  |       |                 |
| Corrective Action: |   | Date: |                 |
| Type:              | #   |       |                 |
| Comment:           | See Inspection Doc # 699305081 for related shared facilities and equipment. |       |                 |
| Corrective Action: |   | Date: |                 |

**Tanks and Berms:**

|                    |   |          |      |         |        |
|--------------------|---|----------|------|---------|--------|
| Contents           | #   | Capacity | Type | Tank ID | SE GPS |
|                    |   |          |      |         |        |
| Comment:           | See Inspection Doc # 699305081 for related shared facilities and equipment. |          |      |         |        |
| Corrective Action: |   | Date:    |      |         |        |

**Paint**

|           |                      |
|-----------|----------------------|
| Condition | <input type="text"/> |
|-----------|----------------------|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 289677 Type: WELL API Number: 123-24893 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA Form 04 (TA)-00 Doc # 402647797, Form 06A Doc # 403108165.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 04/22/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Submit test results to the ECMC.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>ECMC Inspection Report Summary</p> <p>On Thursday 8-17-2023 at approximately 0940 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Oxy/Kerr McGee</p> <p>Location name: Cannon-USX W 15-8</p> <p>API #05-123-24893</p> <p>County: Weld</p> <p>Weather: Clear, Sunny.</p> <p>Location: Dry.</p> <p>While there, I observed a wellsite, TA at the time of the inspection.</p> <p>During this inspection, I observed no compliance issues:</p> <p>See attached photos.</p> <p>No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p> | revasr | 08/17/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 702402228    | location pics | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223561">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223561</a> |