

Inspection Photos

API: 071-09549

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2023



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 1. Facing northwest along the main access road. There is an abandoned pipe riser that still remains. No active well sites exist in this area and the riser needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 2. Facing west toward the access road which remains per approved variance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 3. Facing southeast along the access road which remains per approved variance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 4. Facing southeast along the portion of the road that was fully reclaimed.



Inspection Photos



Photo 5. There are noxious weeds at red arrow (Canada thistle) which are wilted from recent weed control.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 6. Facing southeast toward the bottom portion of the location. The location is recontoured and vegetation is progressing well..



Inspection Photos



Photo 7. Facing west toward the reclaimed the location. The location is recontoured and vegetation is progressing well.



Inspection Photos



Photo 8. Facing southwest at the location. There are numerous noxious weeds in this area. Some are wilted and controlled but some are not. Follow up weed control will need to be performed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 9. Facing northwest toward the reclaimed the location. The location is recontoured and vegetation is progressing well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 10. Facing southeast toward the reclaimed the location. The location is recontoured and vegetation is progressing well.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09549 | Date: 8/16/2023

Inspection Photos



Photo 11. There are noxious weeds at the top portion of the location that have not been controlled. Red arrow points to Canada thistle.

