

Inspection Photos  
Maralex Gosney 2A  
API 067-09798



**Photo #1. Disconnected, flammable materials stored near wellhead.**



**Photo #2. Produced water tank volume capacity not labeled.**



Inspection Photos  
Maralex Gosney 2A  
API 067-09798



**Photo #3. View of unused equipment stored on ground.**



**Photo #4. Impacted material on ground around prime mover.**

