

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2023

Submitted Date:

08/18/2023

Document Number:

712700541

FIELD INSPECTION FORMLoc ID 325536 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		Maralextech@gmail.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214965	WELL	PR	06/16/2021	GW	067-06570	GOSNEY 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
Lease Road:				
Type	Access			
comment:	Road through active gravel operations.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Present			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds growing around separator.			
Corrective Action:	Remove weeds per Rule 606.			Date: 09/01/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Concrete jersey barriers			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Concrete jersey barriers			
Corrective Action:				Date:
Equipment:				
Type: Deadman # & Marked	# 4			corrective date
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	3" line from separator to inline digital meter.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Telemetry			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	3" line from wellhead to separator. 3" line from separator to inline meter.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 214965 Type: WELL API Number: 067-06570 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 07/26/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No Form 17 in well file for 2023.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700548	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225060