

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC H36X Pad**  
**Location ID: 335003**



**Photo # 6020 From entrance to location**



**Photo # 6021 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC H36X Pad**  
**Location ID: 335003**



**Photo # 6022 Location**




**Photo # 6023 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC H36X Pad**  
**Location ID: 335003**



**Photo # 6024 Location**



**Photo # 6025 Debris**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC H36X Pad**  
**Location ID: 335003**



**Photo # 6031 Debris**



**Photo # 6030 Flowline heating insulation open ended**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC H36X Pad**  
**Location ID: 335003**



**Photo # 6032 Flowline heating insulation open ended**