

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1 Pad
Location ID: 334961



Photo # 6156 From entrance to location



Photo # 6157 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1 Pad
Location ID: 334961



Photo # 6158 Location



Photo # 6159 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1 Pad
Location ID: 334961



Photo # 6160 Location

Photo # 6161 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1 Pad
Location ID: 334961



Photo # 6168 Flowline heating insulation open ended



Photo # 6170 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC L1 Pad
Location ID: 334961



Photo # 6171 Open ended load line



Photo # 6172 Open ended load line