

Inspection Photos
Location Name: CAERUS PICEANCE LLC K36B Pad
Location ID: 334899



Photo # 6092 From entrance to location



Photo # 6093 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC K36B Pad
Location ID: 334899



Photo # 6094 Location



Photo # 6095 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC K36B Pad
Location ID: 334899



Photo # 6099 Debris

Photo # 6103 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC K36B Pad
Location ID: 334899



Photo # 6104 Flowline heating insulation open ended