

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Location Overview:** Location is approximately 47 yards from Pete & Bill Creek. Location is within High Priority/NSO/Black Bear Habitat areas.

**Section/Township/Range: 8 8S95W**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6508 BMP needs maintenance, erosion starting to undercut armoring**



**Photo # 6509 BMP needs maintenance, erosion starting to undercut armoring**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6510 Lack of stabilization on slope/insufficient BMP's**



**Photo # 6511 Lack of stabilization on slope/insufficient BMP's/ditch needs maintenance**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6512 Lack of stabilization on slope/insufficient BMP's/ditch needs maintenance**



**Photo # 6513 Lack of stabilization on slope/insufficient BMP's/ditch needs maintenance**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6515 Lack of stabilization on slope/insufficient BMP's**



**Photo # 6524 Erosion & transport of sediment onto location/insufficient run on controls/BMP's (near tank battery)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6525 Erosion & transport of sediment onto location/insufficient run on controls/BMP's (near tank battery)**



**Photo # 6526 Erosion & transport of sediment onto location/insufficient run on controls/BMP's (near tank battery)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6527 Erosion & transport of sediment onto location/lack of stabilization on slope/insufficient run on controls/BMP's (near tank battery)**



**Photo # 6531 Lack of stabilization on slope/erosion & transport of sediment/ditch needs maintenance**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6535 Lack of stabilization on slope/erosion & transport of sediment/insufficient run on controls/BMP's**



**Photo # 6539 Lack of stabilization on slope/erosion & transport of sediment/insufficient run on controls/BMP's**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6540 Erosion & transport of sediment**



**Photo # 6541 Erosion & transport of sediment**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6542 Lack of stabilization on slope/erosion & transport of sediment/insufficient run on controls/BMP's (on lease road near pig station)**



**Photo # 6544 Lack of stabilization on slope/erosion & transport of sediment/insufficient run on controls/BMP's (on lease road near pig station)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6545 Lack of stabilization on slope/erosion & transport of sediment/insufficient run on controls/BMP's (on lease road near pig station)**



**Photo # 6546 Lack of stabilization on slope/erosion & transport of sediment/insufficient run on controls/BMP's (on lease road near pig station)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6532 Erosion & transport of sediment off lease road  
(on lease road near pig station)**



**Photo # 6533 Erosion & transport of sediment off lease road  
(on lease road near pig station)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6547 Erosion & transport of sediment off lease road  
(on lease road near pig station)**



**Photo # 6549 Lack of stabilization on slope/transport of  
sediment onto edge of lease road (approximately 1/10<sup>th</sup> of a  
mile from location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6551 Lack of stabilization on slope/transport of sediment onto edge of lease road (approximately 1/10<sup>th</sup> of a mile from location)**



**Photo # 6552 Lack of stabilization on slope/transport of sediment onto edge of lease road (approximately 1/10<sup>th</sup> of a mile from location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6555 Lack of stabilization on slope/transport of sediment onto edge of lease road (approximately 1/10<sup>th</sup> of a mile from location)**



**Photo # 6556 Lack of stabilization on slope/transport of sediment onto edge of lease road (approximately 1/10<sup>th</sup> of a mile from location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



Aug 18, 2023 at 11:59:58 AM  
CO

**Photo # 6557 Lack of stabilization on slope/transport of sediment onto edge of lease road (approximately 1/10<sup>th</sup> of a mile from location)**



Aug 18, 2023 at 12:02:51 PM  
SO

**Photo # 6561 Sediment trap needs maintenance (on lease road just after the Federal 8D pad location # 415673)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6562 Sediment trap needs maintenance (on lease road just after the Federal 8D pad location # 415673)**



**Photo # 6563 Sediment trap needs maintenance/BMP's need maintenance/erosion & transport of sediment (on lease road just after the Federal 8D pad location # 415673)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6573 Erosion & transport of sediment off lease road  
(approximately 2 miles from location)**



**Photo # 6574 Erosion & transport of sediment  
(approximately 2 miles from location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6575 Erosion & transport of sediment/BMP's need maintenance (approximately 2 miles from location)**



**Photo # 6576 Sediment trap need maintenance (approximately 2 miles from location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad**  
**Location ID: 334081**



**Photo # 6577 Erosion & transport of sediment/BMP's need maintenance (approximately 2 miles from location)**



**Photo # 6578 Erosion & transport of sediment off lease road (approximately 2 miles from location)**