

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2023

Submitted Date:

08/17/2023

Document Number:

696305226

FIELD INSPECTION FORMLoc ID 420179 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 3250

Name of Operator: ANTELOPE ENERGY COMPANY LLC

Address: P O BOX 577

City: KIMBALL State: NE Zip: 69145

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Keeler, Jodi	308-235-4661	jodik@antelope-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420177	WELL	SI	05/01/2023	OW	123-32490	State 9-61-16	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Weeds at Tank Battery; see photos

Corrective Action: Comply with Rule 606

Date: 09/15/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

IGNITOR/COMBUSTOR

Comment: Barbed Wire

Corrective Action:

Date:

Type

TANK BATTERY

Comment: Barbed Wire

Corrective Action:

Date:

Type

SEPARATOR

Comment: Barbed Wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Vertical Heater Treater

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

300 BBLS

FIBERGLASS AST

,

Comment:

Corrective Action:

Date:

Paint

Condition

Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 420177 Type: WELL API Number: 123-32490 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection. Weeds at Tank Battery	petrie	08/17/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403500458	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223148
696305227	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223143