

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2023

Submitted Date:

08/17/2023

Document Number:

712700529

**FIELD INSPECTION FORM**Loc ID 325498 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 25250

Name of Operator: DUGAN PRODUCTION CORP

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Cody		Cody.Wheeler@duganproduction.com	SW Field inspections
Feil, Tyra		tyrafeil@duganproduction.com	SW Field inspections
Alexander, John		johncalexander@duganproduction.com	SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214894	WELL	PR	02/28/2011	GW	067-06498	TIFFANY 1	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #702500652 submitted on 10/24/2022, and FIR Document #702500365 submitted on 8/31/2022.

New corrective actions are identified in this FIR.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Present

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Extensive weeds growing around and among production equipment. See Photos #1-#4.		
Corrective Action:	Keep area free and clear of vegetation and potentially combustible materials per Rule 606.	Date:	08/31/2023
Type	UNUSED EQUIPMENT		
Comment:	Two muffler hoses on ground beside skid compressor. See Photo #		
Corrective Action:	Equipment appear non-servicable, remove all unused/non-servicable equipment per Rule 606.	Date:	08/31/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	T-post and hog wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	And skid compressor, pipe fence.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	3' line from separator to offsite meterhouse. Calibrated within one year.		

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On vent stacks of separator, dehydrator.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	2" line from wellhead to northern separator, line from northern separator to northern produced water tank, 2" line from northern separator to southern separator, 2" line from northern separator to northern produced water tank, 4" line from southern separator to gas meter run off location.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry, cathodic protection.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.036030,-107.581540
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Weeds growing on containment berms and within base.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	<50 BBLs	STEEL AST		37.035750,-107.581450	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Weeds on containment berms and within containment base.					
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass	Ditches	Pass	Material Handling And Spill Prevention	Pass	Container within containment.

Comment: [Location is water saturated.](#)  
[No visible erosion or sediment migration observed during inspection.](#)  
[Corrective action identified in Doc.#702500652 has been completed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT
**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403500938	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223579">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223579</a>
712700532	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223567">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6223567</a>