

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2023

Submitted Date:

08/18/2023

Document Number:

712700542

FIELD INSPECTION FORMLoc ID 414270 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		Maralextech@gmail.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287557	WELL	PR	04/25/2007	CBM	067-09255	GOSNEY 1-A	PR
294961	WELL	PR	08/22/2008	CBM	067-09507	GOSNEY 4-A	PR
414273	WELL	PR	12/01/2010	CBM	067-09798	GOSNEY 2-A	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank volume capacity not labeled.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 10/18/2023
Type	WELLHEAD		
Comment:	Wellhead signage is located on separator shacks.		
Corrective Action:			Date:

Emergency Contact Number:

Comment: Present

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Sections of pumpjack fence panels on ground.		
Corrective Action:	Return to service or remove if non-serviceable or no longer needed for ongoing oil and gas operations.		Date: 09/02/2023
Type	UNUSED EQUIPMENT		
Comment:	Observed disconnected lube oil containers next to wellhead.		
Corrective Action:	Comply with Rule 610.d. by storing flammable liquids greater than 50 feet from the wellbore.		Date: 08/25/2023
Type	WEEDS		
Comment:	Weeds growing around pumpjacks, tank containment berms.		
Corrective Action:	Remove weeds per Rule 606.		Date: 09/01/2023
Type	OTHER		
Comment:	Observed impacted material on ground around prime mover.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.		Date: 08/23/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Randomly positioned concrete jersey barriers near separators and pumpjacks.		
Corrective Action:			Date:

<u>Equipment:</u>			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 3		
Comment:	One not operating, motor not running.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	3-2" lines from wellhead to separators. 3-1" lines from separator to prime mover.		
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	Buried valve can		
Corrective Action:		Date:	
Type: Prime Mover	# 3		
Comment:	Natural gas motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	#		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		37.193130,-107.582160
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Pattillo, Curtis

Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number
067-09507
067-09255

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 287557 Type: WELL API Number: 067-09255 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/26/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No Form 17 in well file for 2023.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.Date:

Facility ID: 294961 Type: WELL API Number: 067-09507 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/27/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No Form 17 in well file for 2023.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.Date:

Facility ID: 414273 Type: WELL API Number: 067-09798 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/28/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 62 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No Form 17 in well file for 2023.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Gravel	Pass	Gravel	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403502451	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225076
712700549	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6225062