

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/26/2023

Document Number:

707601739

FIELD INSPECTION FORMLoc ID 438449 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438450	WELL	PR	06/01/2023	OW	123-39978	Chesnut 27O-243	WK

General Comment:

This is a WORKOVER inspection.

Well(s): 1: Workover | WK.

Workover Ops: Sand clean-out. Day 2.

Battery: Active.

Active Battery SE corner GPS coordinates: 40.370468 / -104.542916

Well GPS coordinates: 40.369471 / -104.540808

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite safety signage posted.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	438450	Type:	WELL	API Number:	123-39978	Status:	PR	Insp. Status:	WK
Workover									
Comment:	<div>Workover Contractor: Ensign Energy Services, Rig #356. Reference: Form 42 on file. Notice of MIRU. Start Date: 08/23/2023. Approved. 2023/08/24: Workover Ops: Sand clean-out. Day 2. 2023/08/24: JSA attached as photo to this report.</div>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On THU 08/24/2023 at approximately 16:44 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: Chesnut/27K-HZ Pad Location ID: 438449 Well Name(s): Chesnut 27O-243. API: 123-39978. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Workover WK. Workover Ops: Sand clean-out. Day 2. Battery: Active. Active Battery SE corner GPS coordinates: 40.370468 / -104.542916 Well GPS coordinates: 40.369471 / -104.540808</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/26/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601740	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237750